

BMW Oil Service

VIN: BJ11195

Model: M5

Body / electrical system

- Heater/air conditioner: change microfilter/carbon canister.
- Check water drain below brake booster for contamination, clean if necessary

Engine compartment

- Change engine oil and oil filter. **(6,5 l)**
- Optional extra 199 "Equipment leaded fuel" only: carry out diagnosis brief test (optional extra 199 can be identified among other by the sticker in the Owner's Handbook "Important Information: Leaded Fuel"). ¹
- Reset service interval indicator as per factory specification.

Chassis area

- Brake pads
 - Check pad thickness with measuring gauge.
 - If changing pads: clean brake pad take-ups. Brake discs: check surface and thickness. If changing at pads at rear: check parking brake linings. Grease wheel centring mount on alloy wheels. ¹
- Parking brake: check function, adjust as per instructions if necessary.

¹ for a separate charge